




Produkt Information

44250010 switch turn signal (with high beam headlight flash, reproduction, only LHD)

Some De Tomaso Pantera have a connector plug that is not compatible with the connector of the switch supplied. In this case, the original plug from the vehicle must be used and the connection cable of the switch supplied must be connected accordingly to the old plug.



Ford Belegung



DeTomaso Belegung